

## ODISHA FIRE SERVICE FIRE SAFETY CERTIFICATE

## FORM-V

[Under rule-13(3) of the Odisha Fire Prevention and Fire Safety Rules, 2017]



Certificate No:	FIRCER1307220032022000776	Application No:	FSC1307220032021001716
Date of Issue:	12-01-2022	Date of Receipt of Application:	31-12-2021
Valid Up to:	11-01-2024 (midnight)		

(Apply for Renewal of Fire Safety Certificate at least three months before its expiry)

Certified that the

ST. MARY'S SCHOOL, TELENPALI, JHARSUGUDA, DIST-JHARSUGUDA

Situated at

Plot No-299/1429, Khata No.-94/130, Street-Telenpali, Mouza-Telenpali, Police Station-25, District-Jharsuguda, Fire Station-Lakhanpur

Consisting of total

1 Number of Towers/Blocks, was inspected by officers of the Fire Service

08-01-2022

In presence of

The Principal



Manager
St. Mary's School
Pali Rapharpali 769224

St. Mary's School Telenpali, Banharpali-768234 Dist- Jharsuguda, Cüisha Page 1 of 2

Principal
St. Mary's School
Telenpali, Banharpali-768234
Dist- Jharsuguda, Odisha

and it has been found to comply with the fire prevention and safety requirements in accordance with the Odisha Fire Prevention and Fire Safety Rules, 2017 read with Odisha Fire Prevention and Fire Safety(Amendment) Rules, 2019 and that its various floors are fit for occupancy or usage as noted hereunder against each subject to compliance to the conditions as prescribed herein below:

1. Name of the Building(s)/Tower(s)/Block(s):-

ST. MARY'S SCHOOL, TELENPALI, JHARSUGUDA, DIST-JHARSUGUDA

\* Floor wise occupancy:-

SI,No.	Floors in Tower/Block	Usage
1	Ground floor, 1st floor & 2nd floor	Educational

## CONDITIONS:-

- 1. Fire prevention and safety measures and appliances, availability of water supplies and means of access thereto etc provided in the building or premises, should be maintained by the occupier(s) in best repairs and efficient working condition at all times for use by the occupants or the members of the Fire Service or both in the event of outbreak of fire.
- The set-backs, driveways, entrance gates, exits, staircases, corridors and escape way should not be changed, obstructed or modified in any way
- 3. The occupiers(s) shall train all staff and occupants periodically to make them well conversant in use and operation of the fire prevention and safety measures.

4. Fire drills/rehearsals should be organised at least once in six months by involving Local Fire Station.

- 5. Photocopies of this Certificate should be framed and displayed at all conspicuous places in all lobbies/corridors in all floors of all Towers/Blocks of building/premises.
- 6. The maintenance of fire safety installation in the building / premise shall be owner's / occupier's liability as per Rule 16 of OFP & FS Rules, 2017. He shall maintain the same in good repairs and working condition at all times. Any lapses in fire safety installation during fire incident if any shall end with owner's / occupier's responsibility.

By order of the Director of Fire Service

Signature yalid

Signed by: SALZ PRAKASI KINDO Date: 12-04 2022 12:05:03

Salil Prakash Kindo

Deputy Fire Officer, Rourkela Circle

## NOTE

(i) It is a digitally signed electronically generated certificate and therefore needs no ink-signed signature.

(ii) This Certificate is issued as per section 4, 5,& 6 of Information Technology Act 2000 and its subsequent amendments in 2008.

(iii)For any Query or Verification , Agency / Department / Office may visit https://agnishamaseva.odisha.gov.in

(iv)Tampering of this Certificate will attract penal action.

St. Mary's School
Telenpali, Banharpali-768234
Dist-Jharsuguda, Cuisha

Principal
St. Mary's School
Telenpali, Banharpali-768234
Dist- Jharsuguda, Odisha